

Electrical PC test 1

Analyser 2

Emergency stop 3

Black box or screen switch 4

Camera light

General switch OFF 5

Low voltage Switch OFF 6

Robot PC 7

Micrometric screw for setting the focus 8

Calibration camera 9

Vibrating rail 10

Vibrating bowl 11

Micrometric screw for setting circuit board position 12


Head n°1 13

Circuit-breaker 14

Position for placing double-sided components under test on the rail

head No.2

OK bin



Head screw 1

Calibration camera

vibrating rails

Acquisition camera.

Test circuit board